

23 October 2025

**Inspection report for conical crusher**

**Location of inspection: Nyamyumba processing plant, Rulindo district  
Rutongo Mines Ltd (Trinity Metals Group)**

**Findings**

The following parts of the conical crusher need repairing:

1. Conical crusher head surface needs to be repaired on deformed surface
2. Spring sleeves worn out. Need to fabricate new spring sleeves
3. Springs are old. Need new springs

Inspection conducted by:

**Habinshuti Jean Damascene**  
**Machines Outils Ltd**  
**Tel: +250786168237/ 0785543885**



In presence of:

**Niyibizi Marcel**  
**Ag. Plant Supervisor**  
**Rutongo Mines Ltd – Trinity Metals Group**  
**Tel: +250783797083**

