RUTONGO
MINES

KARAMBO Engine water Pump maintenance & Service

PR13337	VERY URGENT

Description	GL Account	UOM	Order Qty	Unit Cost	Currency	Estimated Total
Air Filter (for Engine CD4045 / WATER PUMP)	2233-125	EA	1	87,000	RWF	87,000
Alternator (for Engine CD4045 / WATER PUMP	2233-125	EA	1	400,000	RWF	400,000
Fan Belt (for Engine CD4045 / WATER PUMP)	2233-125	EA	1	70,000	RWF	70,000
Thread Locker (for Engine CD4045 / WATER PU	2233-125	EA	1	60,000	RWF	60,000
Engine oil Filter (for Engine CD4045 / WATER F	2233-125	EA	1	82,000	RWF	82,000
Crank Shaft oil Seal (for Engine CD4045/WATE	2233-125	EA	1	55,000	RWF	55,000
TOTAL					**RWF**	**754,000**

APPROVED BY GM:

APPROVED