


Injector Pump Repair For Bobcat

PR8504

| Description | GL Account | UOM | Order Qty | Unit Cost | Currency | Estimated Total |
|--|------------|-----|-----------|-----------|----------|---------------------|
| Tete hydraulique | 2233-502 | EA | 3 | 295,000 | RWF | 885,000 |
| Kit joint de la pompe d'i | 2233-502 | EA | 4 | 29,500 | RWF | 118,000 |
| Electrovane de la pompe d'injecteur rotative | 2233-502 | EA | 1 | 59,000 | RWF | 59,000 |
| Clap de l'electrovane | 2233-502 | EA | 1 | 11,800 | RWF | 11,800 |
| Levier d'accelerateur | 2233-502 | EA | 1 | 17,700 | RWF | 17,700 |
| Boulon de retour | 2233-502 | EA | 2 | 17,700 | RWF | 35,400 |
| Maintenance (Revision + Reglage) | 2233-502 | EA | 4 | 41,300 | RWF | 165,200 |
| TOTAL | | | | | | 1,292,100.00 |

APPROVED BY GM:



1-8-2025