


**Injector Pump Repair For Bobcat**

PR8504

Description	GL Account	UOM	Order Qty	Unit Cost	Currency	Estimated Total
Tete hydraulique	2233-502	EA	3	295,000	RWF	885,000
Kit joint de la pompe d'i	2233-502	EA	4	29,500	RWF	118,000
Electrovane de la pompe d'injecteur rotative	2233-502	EA	1	59,000	RWF	59,000
Clap de l'electrovane	2233-502	EA	1	11,800	RWF	11,800
Levier d'accelerateur	2233-502	EA	1	17,700	RWF	17,700
Boulon de retour	2233-502	EA	2	17,700	RWF	35,400
Maintenance (Revision + Reglage)	2233-502	EA	4	41,300	RWF	165,200
<b>TOTAL</b>						<b>1,292,100.00</b>

APPROVED BY GM:



1-8-2025