


**Tubeless Tyre Repair patch and Valves / Super Critical**

PR10632      **VERY URGENT**

Description	GL Account	UOM	Order Qty	Unit Cost	Currency	Estimated Total
Tubeless Tyre Repair Patch	2233-502	EA	70	2,000	RWF	140,000
Tubeless Tyre Tybe Valve	2233-502	EA	70	1,500	RWF	105,000
<b>TOTAL</b>						<b>245,000</b>



APPROVED BY GM:

