

Picking Slip

Requisition Date: 2025-12-29
Sage Reference: REQ00183494
4Flow Reference: IR0057136
Shipment Number: Not Shipped

Requester:	Cost Centre:	Cost Centre Name	Description:	Ship Date:
Justin Karangwa	100	Nyamyumba	Bousman Maintenance	Not Shipped

Item No.	Location	Item Description	Qty Ordered	UOM	Qty Shipped	Qty Remaining
LOCO071	STCK01	Bucket Motor 271-143b for Bousman	2.00	EA	0.00	2.00
LOCO072	STCK01	Pneumatic Motor for Lifting K141.5.0 for Bousman	6.00	EA	0.00	6.00
LOCO073	STCK01	Pneumatic Motor for Running K141.60 for Bousman	5.00	EA	0.00	5.00
LOCO074	STCK01	Hose Pipe for 30-0800 18.6 for Bousman	20.00	EA	0.00	20.00
LOCO075	STCK01	Chain Assy 21.133 for Bousman	6.00	EA	0.00	6.00
LOCO076	STCK01	Lock Arm 2233-502 for Bousman	3.00	EA	0.00	3.00
LOCO077	STCK01	Bucket Assy 2233-502 for Bousman	2.00	EA	0.00	2.00
LOCO078	STCK01	Air Filter 2233-502 for Bousman	30.00	EA	0.00	30.00
LOCO079	STCK01	Handle Control Parts K141.4-0 for Bousman	12.00	EA	0.00	12.00
LOCO080	STCK01	Bearing End Cao K141.2-25 for Bousman	12.00	EA	0.00	12.00
LOCO081	STCK01	O-Ring 103*3.55 for Bousman	20.00	EA	0.00	20.00
LOCO082	STCK01	Bearing NJ310E for Bousman	25.00	EA	0.00	25.00
LOCO083	STCK01	Lifting Bucket Chain 2233-502 for Bousman	5.00	EA	0.00	5.00
LOCO084	STCK01	Bushing K141.1-32 for Bousman	3.00	EA	0.00	3.00
LOCO085	STCK01	Handle K141.1-60 for Bousman	5.00	EA	0.00	5.00
LOCO086	STCK01	Wire Rope Front Seat 2233-502 for Bousman	6.00	EA	0.00	6.00
LOCO087	STCK01	Chain End Pin K141.2-38 for Bousman	10.00	EA	0.00	10.00
LOCO088	STCK01	Wire Rope Rear SeatK141.2-3 for Bousman	5.00	EA	0.00	5.00
LOCO089	STCK01	Bucket Blade Seal fK141.2-3 for Bousman	5.00	EA	0.00	5.00
LOCO090	STCK01	Section Rubber Seal K141.2-40 for Bousman	5.00	EA	0.00	5.00
LOCO091	STCK01	Wire 5.5-180-X-2(L=1660) for Bousman	10.00	EA	0.00	10.00

Shipper: Not Shipped

Additional Info:

Received by: _____