

PLACIDU COMPANY LTD

TIN: 122379761

Email: gakwayaramadhan@gmail.com

PROFORMA INVOICE



DATE: 16/April/2024

CLIENT: RUTONGO MINES

TIN: 101907021

No	ITEM	DESCRIPTION	TOTAL PRICE
1	Terminal Insulation Maintenance	<ul style="list-style-type: none">Inspect and maintain terminal connections to ensure optimal performance.	1,500,000
2	Assembly and Rewinding of windings	<ul style="list-style-type: none">Disassemble, inspect, and rewind the transformer coils (windings) as needed	1,500,000
3	Replacement of Transformer Commutator	<ul style="list-style-type: none">Replace the commutator to enhance efficiency and reliability	500,000
4	Cleaning of Fumes Inside the Transformer	<ul style="list-style-type: none">Thoroughly clean the interior of the transformer to remove accumulated fumes and contaminantsConduct a thorough inspection of the transformer to identify the root causes of the unbalanced phases and neutral point issues.Use specialized testing equipment to assess winding resistances, insulation integrity, and magnetic balance.	500,000
5	Unbalanced Phases Correction	<ul style="list-style-type: none">Address the unbalanced phases by adjusting the connections and ensuring equal load distribution across all phases.Verify that the current flowing through each phase is within acceptable limits.	1,000,000
6	Maintenance of Both Primary and Secondary Bushings	<ul style="list-style-type: none">Inspect and maintain bushings to ensure proper insulation and functionality	1,000,000
7	labor	<ul style="list-style-type: none">Our skilled technicians will oversee the entire maintenance process	500,000
TOTAL			6,500,000

Bank Details

Account Name: PLACIDU COMPANY LTD.

Account Number: 4492028498

BANK: BPR BANK PLC

Thank you for your business.